



# Map 9 Comparison of 1997 and 2003 Septic Ratings Town of Putney, Vermont

Note: Soils data are generalized, and on-site investigation is required for a definitive analysis of septic suitability. Soils data are from the Vermont Geographic Information System and were developed in conjunction with the Windham County Soil Survey.

- significant suitability decrease (from moderately to marginally)
- some suitability decrease (from well to moderately)
- no change
- some suitability increase (from marginally to moderately)
- significant suitability increase (from not suited to marginally or moderately)

0.5 0 0.5 1 1.5 2 Miles

map produced May 2003  
Windham Regional Commission, Brattleboro, Vt.  
c:\towns\putney\buildout\septic.apr